
# **Operation examples**


#### **Electronic Parts Inspection**

Operate the AX with multiple machines and achieve high tact




## Laser Labeling of Workpieces

Laser marking is done at constant increments.




# Laser Labeling of Workpieces

Laser marking is done at constant increments.




## Conveyor of Electronic Substrate

Rotate electronic substrates by  $90^\circ$ 



#### Pick and Place

Work is conveyed using an equipped parallel displacement mechanism.



# Assembly, Inspection Machines

Conduct setup changes without time loss

